Surface Mount

To + VDC (fuse @ 2A): .....**RED**

To Chassis Ground: .....**BLACK**

For Low Power: .... WHITE
 Apply +VDC to WHITE wire.

For Synchronization ....**YELLOW**
 Connect **YELLOW** wires of multiple lightheads together for synchronization
 (All heads should be set at the same Flash Pattern)

For Simultaneous or Alternating Flash:
 1. Apply +VDC to **RED** and **YELLOW** wires simultaneously to enter Grouping mode;
    lighthead will display short (single or double) flash:
    · Single flash = Group1   · Double flash = Group2

 2. Remove **YELLOW** wire from +VDC then momentarily apply +VDC to change Groups:
    · Heads of the same Group will flash together.
    · Heads of the different Group will flash alternately.

For Flash Patterns:
 Momentarily apply +VDC to **YELLOW** wire:
    · once for next pattern
    · quick three times for pattern 1

NOTE: This unit may not be factory set at FP# 1.

FP#	Flash Patterns
1	Single (R65)
2	Double (R65)
3	Triple (R65)
4	Quad (2Hz)
5	Steady