

Standby brackets and light bars

	Model	Year	Rail type	Bracket	LB200	W-series	VEGA	Other info
BMW	5-serie	2010-2017	Integrated	89500314*		1270	1280	Hole in bracket missing for VEGA
Citroen	Berlingo	2018-	Fixing points	89500164*		1270	1280	
	Jumpy/Spacetourer Jumper	2016-2014-	Fixing points	89500304		1440	1280	
Dacia	Dokker	2012-	Fixing points	89500164*		1270	1280	
Fiat	Doblo	2023-	Fixing points	89500164*		1270	1280	
	Connect Talento Ducato	2013-2016-2014-	Fixing points	89500164* 89500165		1270	1280	
Ford	Ranger	2019-	Detached	89500312		1270	1280	
	Ranger	2022-	Detached	89500161*	1220	1270	1280	
	Transit Connect	2021-	Fixing points	89500164*		1270	1280	
	Transit Custom	2012-	Fixing points	89500304		1600	1590	
	Transit	2013-	Fixing points	89500304		1600	1590	
Hyundai	Tucson	2021-	Integrated	89500318		1270	1280	
Kia	Niro	2017-2021	Integrated	89500315	622/1235/1388/1541	1270	1280	
	Niro	2021-	Integrated			1270	1280	
	Sorento	2023-	Integrated	89500318		1270	1280	
	Sportage	2021-	Integrated	89500318		1270	1280	
Mercedes	Citan	2013-	Fixing points	89500164*		1270	1280	
	Citan	2021-	Fixing points	89500164*		1270	1280	
	Sprinter	2006-	Fixing points	89500165		1600	1590	
	X-Class	2018-	Detached	89500161*		1270	1280	
	Vito	2014-	Fixing points	89500165		1440	1590	
Nissan	Navara	2014-	Detached	89500312		1440	1590	
	NV250	2019-	Fixing points	89500161*		1270	1280	
	Townstar	2021-	Fixing points	89500164*		1270	1280	
	NV300	2016-	Fixing points	89500165		1600	1590	
	Primastar	2022-	Fixing points	89500165		1600	1590	
	NV400	2010-	Fixing points	89500304		1600	1590	
	Interstar	2022-	Fixing points	89500304		1600	1590	
Peugot	Boxer	2014-						
	Partner	2018-	Fixing points	89500164*		1270	1280	
Opel	Combo	2018-	Fixing points			1270	1280	
	Mokka X	2013-	Integrated	89500316*				Hole missing
	Mokka X	2016-	Integrated	89500316*				Hole missing
	Movano	2010-	Fixing points	89500304				
	Movano	2021-						
	Vivaro	2014-	Fixing points	89500165				
Renault	Vivaro	2019-	Fixing points	89500304		1440	1280	
	Alaskan	2018-	Detached	89500161*		1270/1440	1280	
	Express	2021-	Fixing points	89500164*		1100	1280	
	Kangoo	2008-	Fixing points	89500164*		1270	1280	
	Kangoo Master	2021-2010-	Fixing points	89500164* 89500304		1270 1600	1280 1590	
Skoda	Trafic	2014-	Fixing points	89500165		1600	1590	
	Karoq	2017-	Detached	89500301/89500138*		1270	1280	
	Kodiaq	2016-	Detached	89500301/89500138*		1270	1280	
	Enyaq	2020-	Integrated	89500315	622/1235/1388/1541	1270	1280	
	Fabia	2015-	Detached	89500160*		1100	1280	
	Fabia Kombi	2015-	Detached	89500301/89500138*		1100	1280	
	Octavia	2013-	Detached	89500301/89500138*		1270	1280	
	Octavia	2020-	Integrated	89500318		1270	1280	
	Superb	2015-	Detached	89500301/89500138*		1270	1280	
	Yeti	2009-	Detached	89500161*		1270	1280	
Volvo	V70	2007-2016	Detached	89500309*		1270		Hole missing
	XC70	2007-2016	Detached	89500309*		1270		Hole missing
	V60	2010-2018	Integrated	89500303*		1270	1280	
	XC60	2008-2018	Integrated	89500303*		1270	1280	
	V90	2016-	Integrated	89500318		1270	1280	
	V90 XC	2017-	Integrated	89500318		1270	1280	
	XC 90	2015-	Integrated	89500318		1270	1280	
	V60	2019-	Integrated	89500318		1270	1280	
	V60 XC	2019-	Integrated	89500318		1270	1280	
	XC60	2015-	Integrated	89500318		1270	1280	
VW	XC40	2018-	Integrated	89500318		1270	1280	
	Amarok	2017-	Fixing points	89500323*		1440	1280	
	Amarok	2023-	Detached	89500161*	1220	1270	1280	
	Caddy	2008-	Fixing points	89500164*		1100/1270	1280	
	Caddy	2015-	Detached	89500312		1100/1270	1280	
	Caddy	2020-	Fixing points	89500164*		1270	1280	
	Caddy	2020-	Detached	89500312		1270	1280	
	Crafter	2017-	Fixing points	89500165		1600	1590	
	ID4	2020-	Integrated	89500315		1270	1280	
	ID Buzz	2022-	Fixing points	89500304	1373	1440		
	Golf	2018-	Detached	89500312		1100	1280	
	Passat (B7)	2010-2014	Detached	89500307*		1270		Hole missing
	Passat Alltrack (B7)	2012-2015	Detached	89500307*		1270		Hole missing
	Passat (B8) 2015-	2015-	Integrated	89500315	622/1235/1388/1541	1270	1280	
	Passat (B9)	2023-	Integrated	89500315		1270	1280	
	TS	2003-2015	Fixing points	89500304	622/1235/1388/1541	1440	1590	
	TS	2003-2015	Takskena	89500304	622/1235/1388/1541	1440	1590	
	T6 (Trp, Carav, Multiv)	2016-	Fixing points	89500304	622/1235/1388/1541	1440	1590	
	T6 (Trp, Carav, Multiv)	2016-	Rails	89500304	622/1235/1388/1541	1440	1590	
	T-Cross	2019-	Detached	89500312		1270	1280	
T-Roc	2019-	Detached	89500312		1270	1280		
Tiguan	2016-	Detached	89500301/89500138*		1270	1280		
Touareg	2019-	Integrated	89500315	622/1235/1388/1541	1270	1280		
Toyota	Auris Kombi	2013-2018	Integrated	89500315	622/1235/1388/1541	1270	1280	Bracket needs adjustment
	Hilux	2016-						
	Corolla Cross	2022-		89500160*		1270	1280	
	Corolla Cross	2022-	Integrated	89500166		1270	1280	
	Corolla Touring Sports	2019-	Integrated	89500324		1270	1280	
	Proace City	2019-	Fixing points	89500164*		1270	1280	
	Proace	2016-	Fixing points	89500304		1440	1280	
	Rav4	2013-2018	Detached	89500305		1270	1280	
	Rav4	2018-	Integrated	89500166		1270	1280	
	Yaris Cross	2020-	Integrated	89500324		1270	1280	
Yaris	2010-		89500159*		1100	1280		

*Bracket not compatible with LB200