

## Standby brackets and light bars

	Model	Year	Rail type	Bracket	LB200	W-series	VEGA	Other info
BMW	5-serie	2010-2017	Integrated	89500314*	1220	1270	1280	Only for W-lightbar
Citroen	Berlingo	2018-	Fixing points	89500164	1220	1270	1280	
	Jumpy/Spacetourer	2016-	Fixing points	89500304		1440	1280	
	Jumper	2014-						
Dacia	Dokker	2012-	Fixing points	89500164	1220	1270	1280	
Fiat	Doblo	2023-	Fixing points	89500164	1373	1270	1280	
	Connect	2013-	Fixing points	89500164	1220	1270	1280	
	Talento	2016-	Fixing points	89500165				
	Ducato	2014-						
Ford	Ranger	2019-	Detached	89500312	1220	1270	1280	
	Ranger	2022-	Detached	89500161*	1220	1270	1280	
	Transit & Tourneo Connect	2021-	Fixing points	89500164	1220	1270	1280	
	Transit & Tourneo Connect	2021-	Detached	89500312	1220	1270	1280	
	Transit Custom	2012-	Fixing points	89500304		1600	1590	
	Transit	2013-	Fixing points	89500304		1600	1590	
Hyundai	Tucson	2021-	Integrated	89500318	1220	1270	1280	
Kia	Niro	2017-2021	Integrated	89500315	1220	1270	1280	
	Niro	2021-	Integrated		1220	1270	1280	
	Sorento	2023-	Integrated	89500318	1220	1270	1280	
	Sportage	2021-	Integrated	89500318	1220	1270	1280	
Mercedes	Citan	2013-	Fixing points	89500164	1220	1270	1280	
	Citan	2021-	Fixing points	89500164	1220	1270	1280	
	Sprinter	2006-	Fixing points	89500165		1600	1590	
	X-Class	2018-	Detached	89500161*	1220	1270	1280	
	Vito/V-klass	2014-	Fixing points	89500165		1440	1590	
Nissan	Vito/V-klass	2014-	Detached	89500312		1440	1590	
	Navara	2014-	Detached	89500161*	1220	1270	1280	
	NV250	2019-	Fixing points	89500164	1220	1270	1280	
	Townstar	2021-	Fixing points	89500164	1220	1270	1280	
	NV300	2016-	Fixing points	89500165				
	Primastar	2022-	Fixing points	89500165		1600	1590	
Peugot	NV400	2010-	Fixing points	89500304		1600	1590	
	Interstar	2022-	Fixing points	89500304		1600	1590	
	Boxer Partner	2014-2018-	Fixing points	89500164	1373	1270	1280	
Opel	Combo	2018-	Fixing points		1220	1270	1280	
	Mokka	2013-	Integrated	89500316*	1220			Hole missing
	Mokka X	2016-	Integrated	89500316*	1220			Hole missing
	Movano	2010-	Fixing points	89500304				
	Movano	2021-						
	Vivaro	2014-	Fixing points	89500165				
Renault	Vivaro	2019-	Fixing points	89500304		1440	1280	
	Alaskan	2018-	Detached	89500161*		1270/1440	1280	
	Express	2021-	Fixing points	89500164		1100	1280	
	Kangoo	2008-	Fixing points	89500164	1220	1270	1280	
	Kangoo	2021-	Fixing points	89500164	1220	1270	1280	
	Master	2010-	Fixing points	89500304		1600	1590	
Skoda	Trafic	2014-	Fixing points	89500165		1600	1590	
	Karoq	2017-	Detached	89500138*	1220	1270	1280	
	Kodiaq	2016-2024	Detached	89500138*	1220	1270	1280	
	Kodiaq	2025-	Integrated	89500318	1220	1270	1280	
	Enyaq	2020-	Integrated	89500315	1220	1270	1280	
	Fabia Kombi	2015-	Detached	89500138*	1220	1100	1280	
	Octavia	2013-	Detached	89500138*	1220	1270	1280	
	Octavia	2020-	Integrated	89500318	1220	1270	1280	
Volkvo	Superb	2015-	Detached	89500138*	1220	1270	1280	
	Yeti	2009-2017	Detached	89500161*	1220	1270	1280	
	V70	2007-2016	Detached	89500309*	1220	1270		Hole missing
	XC70	2007-2016	Detached	89500309*	1220	1270		Hole missing
	V60	2010-2018	Integrated	89500303*	1220	1270	1280	
	XC60	2008-2018	Integrated	89500303*	1220	1270	1280	
	V90	2016-	Integrated	89500318	1220	1270	1280	
	V90 XC	2017-	Integrated	89500318	1220	1270	1280	
	XC 90	2015-	Integrated	89500318	1220	1270	1280	
	V60	2019-	Integrated	89500318	1220	1270	1280	
	V60 XC	2019-	Integrated	89500318	1220	1270	1280	
	XC60	2015-	Integrated	89500318	1220	1270	1280	
	XC40	2018-	Integrated	89500318	1220	1270	1280	
	VW	Amarok	2017-	Fixing points	89500323*	1373	1440	1280
Amarok		2023-	Detached	89500161*	1220	1270	1280	
Caddy		2008-	Fixing points	89500164	1220	1100/1270	1280	
Caddy		2015-	Detached	89500312	1220	1100/1270	1280	
Caddy		2020-	Fixing points	89500164	1220	1270	1280	
Caddy		2020-	Detached	89500312	1220	1270	1280	
Crafter		2017-	Fixing points	89500165		1600	1590	
ID4		2020-	Integrated	89500315	1220	1270	1280	
ID7		2024-	Integrated	89500315	1220	1270	1280	
ID Buzz		2022-	Fixing points	89500304	1373	1440		
Golf		2018-	Detached	89500312	1220	1100	1280	
Passat (B7)		2010-2014	Detached	89500301	1220	1270	1280	
Passat Alltrack (B7)		2012-2015	Detached	89500301	1220	1270	1280	
Passat (B8) 2015-		2015-	Integrated	89500315	1220	1270	1280	
Passat (B9)		2023-	Integrated	89500315	1220	1270	1280	
T5		2003-2015	Fixing points	89500304	1373	1440	1590	
T5		2003-2015	Taksena	89500304	1373	1440	1590	
T6 (Trp, Carav, Multiv)		2016-	Fixing points	89500304	1373	1440	1590	
T6 (Trp, Carav, Multiv)		2016-	Rails	89500304	1373	1440	1590	
Tayron		2025-	Integrated	89500315	1220	1270	1280	
T-Cross	2019-	Detached	89500312	1220	1270	1280		
T-Roc	2019-	Detached	89500312	1220	1270	1280		
Tiguan	2016-	Detached	89500138*	1220	1270	1280		
Touareg	2019-2023	Integrated	89500315	1220	1270	1280		
Touareg	2024-	Integrated		1220	1270	1280		

Toyota	Auris Kombi	2013-2018	Integrated	89500315	1220	1270	1280
	Hilux	2016-			1220	1280	1280
	Corolla Cross	2022-	Integrated	89500324	1220	1270	1280
	Corolla Touring Sports	2019-	Integrated	89500324	1220	1270	1280
	Proace City	2019-	Fixing points	89500164	1220	1270	1280
	Proace	2016-	Fixing points	89500304	1373	1440	1280
	Rav4	2013-2018	Detached	89500305	1220	1270	1280
	Rav4	2018-	Integrated	89500166	1220	1270	1280

\*Bracket not compatible with LB200